


CORNER RECORD

City of San Leandro County of Alameda, California
Brief Legal Description Monument @ Primrose Dr & Orchard Dr



CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐
Date of Survey Feb 11 2016

COORDINATES (Optional)

N. 2085190.907
E. 6086466.273
Zone NAD83 ☒ NAD27 ☐
Elev. NAD83 Epoch
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☒

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Per section 8771.6 of the Business and Professions Code
This monument was referenced prior to a construction project in the vicinity

A description of the physical condition of the monument as found and as set or reset:

Found in good condition

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed Joseph M. Brajkovich P.L.S. or R.C.E. No. 5254




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 25 FEBRUARY, 2016

and examined and filed 18 MARCH, 2016

Signed Michael Rubner P.L.S. or R.C.E. No. 6843

Title COUNTY SURVEYOR



County Surveyor's Comment _____

